



VIEW OF BOX WITH THE LID REMOVED




PT#	pcs	PARTS	L	W	T	MATERIAL
CUTTING LIST FOR MAIN BOX						
A	2	BOX SIDES	10'	4 1/2'	1/2'	PINE
B	2	BOX ENDS	5 1/2'	4'	1/2'	PINE
C	1	BOX LID	11 1/2'	5 1/2'	1/2'	PINE
D	1	BOX BOTTOM	9 1/2'	5 1/2'	1/4'	PLYWOOD
E	2	BOX STRIPS	9'	1/2'	1/4'	PINE
CUTTING LIST FOR TRAY						
F	2	TRAY SIDES	4 15/16'	2'	3/8'	PINE
G	2	TRAY ENDS	3'	2'	3/8'	PINE
H	1	TRAY BOTTOM	4 9/16'	2 5/8'	1/8'	PLYWOOD



FRONT VIEW

BOTTOM, SUPPORT AND LID
GROOVES 1/4" DEEP



SECTION VIEW